2010-2016 Hyundai Genesis Coupe









AIR CONDITIONER: Confirm that the air conditioner pumps cool air into the cabin within seconds of activation. If not, have the system investigated for potential issues.





ACCESSORIES: Reported problems include power seat adjusters, power windows, and remote keyfobs, so check each on your testdrive.Double-check push-button start system, too.





CHECK THE BODY: Look for misaligned panels, particularly where the hood and fenders meet. If you notice anything suspicious, the vehicle may have been poorly repaired after an accident.





ASSUME THE WORST: Approach a used model assuming it needs new tires and brakes, until you or a mechanic confirm otherwise. Be sure the seller isn't trying to pass off a pricey repair.





PUSH BUTTON START: The push-button start system should fire the engine up the instant its pressed. Any delay or sporadic opreation could indicate a problem with the button, or its internal switch.





LISTEN BENEATH: Note that clunking, popping or snapping noises from beneath the car on a rougher road typically indicate worn suspension components that will require attention from a mechanic. Be alert!





TURBO CHECK: On a turbocharged model, start the engine from cold and let it idle up to operating temperature without driving. White tailpipe smoke in this situation could indicate a bad turbo.





TRANSMISSION: On a manual-equipped model, note that any persistent grinding or 'biting back' through the shifter while changing gears could be signs of excessive transmission or clutch wear.





MODS: Low-quality aftermarket parts, or installation thereof, can cause issues with durability, safety and longevity of all associated components. The average shopper should avoid a modified model.









- Reviews
- Tips
- Buyers Guides
- Shopping Tips

www.justinpritchard.ca